

Safety Rules

[← Back to Onefinity hub](#)

Safety Rules

Read this before operating the machine. These rules apply every time you use the Onefinity CNC - no exceptions.

- **Training required** - members only; request class on Slack **#class-requests**
 - **Never leave the machine unattended** while cutting
 - **Approved materials:** wood and plastics only - **no metals**
 - Dust and chip hazards; fire risk from fine wood dust - **especially important until dust collection is installed**
 - **E-stop** stops machine motion and spindle; does not shut down the shop PC
 - Wear safety glasses; hearing protection recommended
-

[← Hub](#) | Next: [Hardware and Machine Anatomy](#) →

Revision #4

Created 2026-06-22 21:50:06 UTC by Spencer

Updated 2026-06-22 22:23:44 UTC by Spencer